

INSTRUMENT PANEL LIGHTS

Subject: INSTRUMENT PANEL LIGHTS (the first 100 bikes)

Model: Breva 750

Problem:

the instrument panel plastic parts touch a transistor that turns on or off some lights in an erratic way.

Solution:

change the instrument panel.