



REV COUNTER

Subject: rev counter

Model: Nevada 750

Problem:

erratic rev counter

This problem is under analysis, up to now we have found the following possible causes:

- rev counter not working with high air temperature
- water in the main wiring harness, at the curve next to the rear brake master cylinder.